



Block 1 – cluster a external work in progress.



Block 1 – cluster a east side external plastering work in progress.



Block 1 – cluster b 1st floor tile work in progress.



Block 1 – cluster b ceiling putty work in progress.



Block 1 – cluster a putty work in progress.



Block 1 – cluster a internal plasteringwork in progress.



Block 1 – cluster B tile work in progress.



Block 1 – cluster B external plastering work in progress.



Block 1 – Cluster C Tile Work in Progress.




Block 1 – Cluster C upvc window fixing work in progress.




Block 1 – cluster d ceiling & wall putty & primer work in progress.



Block 1 – Cluster D Tile Laying Work In Progress.



Block 1 – Cluster D External Work In Progress.



Block 1 – Cluster D Frame & Shutter Fixing Work In Progress.



Cluster e ceiling & wall putty work in progress.



Cluster E staircase granite laying work in progress.



Cluster E tile work in progress.



Cluster E terrace water proofing work in progress.




Block 1 – Cluster F external work in progress.




Block 1 – Cluster F doors & frames work in progress.



Block 2 – Cluster G 4th floor block work in progress.




Block 2 – Cluster G OHT shuttering work in progress.




Block 3 – Cluster J East elevation external painting work in progress.



Block 3 – Cluster H & J podium waterproofing work in progress.



Block 3 – Cluster J staircase handrail fixing work in progress.



Block 3 – Cluster J Painting Work In Progress.



External sewage pipe laying work in progress.